




Model	Name	Article No	Date	Revision	Revision date
Wildcat Mk1 and Mk2	Repair Kit Wildcat MKI & MKII	9013	2020-02-04	EN.20.01	2020-05-12




A




B






G1



G2



Model	Name	Article No	Date	Revision	Revision date
Wildcat Mk1 and Mk2	Repair Kit Wildcat MKI & MKII	9013	2020-02-04	EN.20.01	2020-05-12

NO	ART. NO	DESCRIPTION	NO	ART. NO	DESCRIPTION
A9	19703	O-ring 10 x 2 NBR 70 (.177, .22, 25, .30)	<div style="text-align: center;">  </div>		
A9B - .30	19210	O-ring 11 x 1,5 NBR 70 (.30)			
A10 - .177	2529	O-ring 4,3 x 1,5 NBR 70			
A10 - .22	19726	O-ring 5,5 x 1,5 NBR 70			
A10 - .25	2575	O-ring 6,35 x 1,27 NBR 70			
A10 - .30	19209	O-ring 7,5 x 1,5 NBR 70			
B2	19485	O-ring 23 x 2,5 NBR 70			
B9	5005	Plastic Washer 2mm 1/8"			
B12	5111	O-ring 2,5 x 1,5 NBR 90			
G1-13	19060	Valve Seat SHP Complete			
G1-14	7052	Valve Pin Wildcat SHP Cpl.	1 -5,5	5108	O-ring 5,28x1,78 Pur 70
G1-16	4528	O-ring 7,66 x 1,78 NBR 70	1 -6,35	2575	O-ring 6,35x1,27 NBR70 (mk1 and mk2, see A10 .25)
G1-18	11507	Rubber/Steel Washer	2	5112	O-ring 5,28x1,78 NBR70
G1-19	19486	O-ring 8,3 x 2,4 NBR 70	3	5112	O-ring 5,28x1,78 NBR70
G1-20	19550	Valve Bushing 5,4mm	<div style="text-align: center;">  </div>		
G1-32	5102	O-ring 2,57 x 1,78 NBR 90			
G2-4	5005	Plastic Washer 2mm 1/8"			
<div style="text-align: center;">  </div>			4	19497	O-ring 23,3x2,4 NBR 70
			18	5109	O-ring 11,6x2,4 NBR70
6.2	5121	O-ring 11.1x1.78 NBR70			
6.4	19109	O-ring 4x1.5 NBR70			
6.8	19485	O-ring 23x2.5 NBR70			
6.10	19485	O-ring 23x2.5 NBR70			
6.13	19731	O-ring 2x1 NBR90			
6.16	19332	O-ring 5x2 NBR70			
6.19	19109	O-ring 4x1,5 NBR 70			